

1

Technical design note

Project name	Land Adjacent Haldens Parkway, Thrapston, Northar	nptonshire	
Design note title	Site Condition Report to support a Deposit for Recovery Permit Application		
Document reference	Report Reference 23880-HYD-XX-XX-RP-GE-5001-	S1-P01	
Author	Eric Cooper MSc C.Geol. SiLC		
Revision	02		
Date	8 August 2023	Approved	

1. Context and Objectives

Equites Newlands (Thrapston East) Limited (Newlands) intends developing an approximate 75 ha (185 acre) site, located to the north of the A14 on the eastern edge of Thrapston, Northamptonshire, for logistical warehousing. The earthworks required to create the development platform will involve the recovery of waste from the Rectory Farm Landfill (permit now surrendered) and its re-use to form landscaped bunds. These works will be carried out by Mick George Limited under contract to Newlands.

The works will be regulated under a Deposit for Recovery Permit (DfR) issued to Mick George Earthworks Limited by the Environment Agency (EA).

This Site Condition Report has been prepared to accompany an application by Mick George Earthworks Limited to the EA for the DfR permit required. More specifically it is submitted in response to Question 5b of Application Form Part B2 -General.

The presentation format accords with the template available at:

https://www.gov.uk/government/publications/environmental - permitting - h5 - site - condition - report.

2. Drawings

The following drawings are attached at Appendix A:

- » 261190_DFR_5A-DfR Site Plan
- » 18443-HYD-XX-ZZ-DR-GE-1001: Site Location Plan
- » 18443-HYD-XX-ZZ-DR-GE-1003: Site Features Plan (undeveloped conditions)
- » 18443-HYD-XX-ZZ-DR-GE-1028 Landscape Bund Layout (bund footprint is Deposit for Recovery Area)
- » 18443-HYD-XX-ZZ-DR-GE-1034_S2-P01_Cross-sections_Bund
- » HRT-pHp-01-XX-DR-A-4432-012-P18: Development Proposals (indicative masterplan for illustrative purposes only)



3. Site Condition Report (Completed Template)

1.0 SITE DETAILS	
Name of the applicant	Mick George Earthworks Limited
Activity address	Land Adjacent Haldens Parkway, Thrapston, Northamptonshire Titchmarsh Road Thrapston Northamptonshire NN14 4NJ
National grid reference	501800E, 278350N
Document reference and dates for Site Condition Report at permit application	Report Reference 23880-HYD-XX-XX-RP-GE-5001-S1-P01
Document references for site plans (including location and boundaries)	The following drawings are attached at Appendix A: » 18443-HYD-XX-ZZ-DR-GE-1001; Site Location Plan » 18443-HYD-XX-ZZ-DR-GE-1003 Site Features Plan: undeveloped (current) conditions » HRT- pHp-01-XX-DR-A-4432-012-P18 Development Proposals (masterplan) » 18443-HYD-XX-ZZ-DR-GE-1028 Landscape Bund Layout (bund footprint is Deposit for Recovery Area) » 18443-HYD-XX-ZZ-DR-GE-1034_S2-P01_Cross-sections_Bund

2.0 Condition of the land at permit issue	
Environmental setting including:	Geology
motading.	(Further details are presented in reports referenced at 2.0 (Supporting Information) below)
» geology» hydrogeology» surface waters	The natural geology is glacial drift, including glacio-fluvial deposits (sand and gravel) overlying a stratified sequence of Jurassic strata. It was the sand and gravel that was exploited by the quarry to create the void that was backfilled with waste.
	The natural geological sequence in the area that is beneath and potentially within influential distance of the landfill is:
	» Glacial Till (Oadby Member), comprising grey or brown clay with subordinate lenses of sand and gravel; and
	» Glaciofluvial Deposits comprising sands and gravels.
	These superficial deposits overlie the solid geology, which comprises:
	» Oxford Clay Formation, comprising silicate mudstone with sporadic beds of limestone; over

2.0 Condition of the land at permit issue				
	» Kellaways Sand Member comprising silicate sandstone and siltstone, pale grey with interbeds of sandy and silty mudstone; over			
	» Kellaways Clay Member outcropping in the south, centre and north-west of the site, comprising grey mudstone; over			
	 Cornbrash Limestone Formation, comprising fine grained, bluish grey, weathering olive or yellow brown limestone; over 			
	» Blisworth Clay Formation, comprising silicate mudstone, grey with frequent fossils, rootlets and ironstone nodules; over			
	» Blisworth Limestone Formation, comprising pale grey or off-white yellowish limestone; over			
	» Rutland Formation, comprising grey mudstone and siltstone; over			
	» Stamford Member, comprising grey to yellowish and white sandstone or siltstone.			
	Hydrogeology			
	(Further details are presented in reports referenced at 2.0 (Supporting Information) below)			
	The Glaciofluvial Deposits, Kellaways Sand Member and the Cornbrash Formation are classified as 'Secondary A' aquifers. The Oadby Member is classified as a 'Secondary Undifferentiated' aquifer. The Blisworth Limestone Formation is classified as a 'Principal' aquifer. The Oxford Clay Formation, Kellaways Clay Member and Blisworth Clay Formation are classified as unproductive strata. Each of the other geological units are noted as 'Unproductive Strata'.			
	The site is not within a Source Protection Zone and there are no active licensed groundwater abstractions within 1km of the site.			
	There is unconfined groundwater present in the landfill as leachate, which was recorded by Hydrock at depths between 0.12m (64.31m OD) and 4.03m (55.58m OD) with a groundwater flow direction towards the north-east.			
	Off the landfill site to the north east, groundwater is present in the more permeable Kellaways Sand formation, the Cornbrash Formation and the Blisworth Limestone Formation. These units are separated by lower permeability units comprising the Kellaways Clay and the Blisworth Clay. The concept is of a layered sequence of aquifers and aquicludes.			
	Surface Waters			
	A series of ditches are present in the land east and north east of the landfill, which coalesce to join Polopit Brook. Under current conditions these ditches are normally dry and only flow after rainfall and are not supported by noticeable baseflow. All flow eventually joins the river Nene.			
Pollution history	Pollution incidents that may have affected land			
including:	Table 2.9 Section 2.11 of the desk study referenced below in Supporting Information notes:			
» pollution incidents	» no Local Authority Pollution Prevention and Controls within 500m of the			

- » no Local Authority Pollution Prevention and Controls within 500m of the site boundary;
- there is a record of a minor pollution incident 81m south west of the site boundary;
- » there are no records of pollution incidents on the site itself.

Historical land-uses and associated contaminants

that may have

affected land

and associated

contaminants

5001-S1-P01 | 8 August 2023

historical land-uses

any visual/olfactory evidence of existing contamination



wevidence of damage to pollution prevention measures """ the most significant potentially contaminative use is the Rectory Farm Landfill, the recovery of which is the subject of the DfR permit application to which this SCR relates: """ most of the rest of the site is greenfield farm land with minor contaminative use associated with farm buildings and some very old stone pits. """ Any visual/olfactory evidence of existing contamination None Evidence of damage to pollution prevention measures There are no pollution prevention measures present at the site. The Hydrock Ground Investigation Report. (Geo-environmental Interpretation) referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports applicable to the site. All relevant data are contained in: """ Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005.		
by evidence of damage to pollution prevention measures """ the most significant potentially contaminative use is the Rectory Farm Landfill. the recovery of which is the subject of the DfR permit application to which this SCR relates: """ most of the rest of the site is greenfield farm land with minor contaminative use associated with farm buildings and some very old stone pits. """ Any visual/olfactory evidence of existing contamination None Evidence of damage to pollution prevention measures There are no pollution prevention measures There are no pollution prevention measures present at the site. Evidence of historic contamination, for example, historical site investigation, assessment, remediation, and verification reports (""") and verification reports ("") and verification reports ("") and verification reports ("") and verification reports ("") and verification reports applicable to the site. There are no remediation and verification reports applicable to the site. All relevant data are contained in: """ Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: """ Appendix C: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. """ Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. """ Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. """ Appendix C: Hydrock, 29 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Inv	2.0 Condition of the land	
to pollution prevention measures Landfill, the recovery of which is the subject of the DfR permit application to which this SCR relates; most of the rest of the site is greenfield farm land with minor contaminative use associated with farm buildings and some very old stone pits. Any visual/olfactory evidence of existing contamination None Evidence of damage to pollution prevention measures There are no pollution prevention measures present at the site. The Hydrock Ground Investigation Report. (Geo-environmental Interpretation) referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial Land use. There are no remediation and verification reports applicable to the site. Where available) Baseline soil and groundwater reference data All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Cround Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Cround Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Cround Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock, 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-003. Historical Ordnance Survey plans	at permit issue	
mission trested with farm buildings and some very old stone pits. Any visual/olfactory evidence of existing contamination None Evidence of damage to pollution prevention measures There are no pollution prevention measures present at the site. The Hydrock Ground Investigation Report. (Geo-environmental Interpretation) referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports applicable to the site. All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Source information incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock, 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	to pollution	Landfill, the recovery of which is the subject of the DfR permit application
None Evidence of damage to pollution prevention measures There are no pollution prevention measures There are no pollution prevention measures present at the site.	measures	contaminative use associated with farm buildings and some very old stone
None Evidence of damage to pollution prevention measures There are no pollution prevention measures There are no pollution prevention measures present at the site.		Any visual/olfactory evidence of existing contamination
There are no pollution prevention measures present at the site. Evidence of historic contamination, for example, historical site investigation, assessment, remediation and verification reports (CPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports applicable to the site. There are no remediation and verification reports applicable to the site. All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix C: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		None
Evidence of historic contamination, for example, historical site investigation neports (Geo-environmental Interpretation) referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports applicable to the site. All relevant data are contained in: Appendix C. Hydrock, 09 December 2023, Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Supporting Information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B. Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C. Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D. Hydrock, 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		Evidence of damage to pollution prevention measures
referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports (where available) Baseline soil and groundwater reference data All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		There are no pollution prevention measures present at the site.
referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports (where available) Baseline soil and groundwater reference data All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		
referenced below reports that, for the site as a whole, laboratory results recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports (where available) Baseline soil and groundwater reference data All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	E	
recorded the majority of chemicals of potential concern (CoPC) at concentrations below the relevant GACs for a commercial land use. There are no remediation and verification reports applicable to the site. All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix E: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		
There are no remediation and verification reports applicable to the site. There are no remediation and verification reports applicable to the site. All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	example, historical site	recorded the majority of chemicals of potential concern (CoPC) at
All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	_	
Mere available) Baseline soil and groundwater reference data All relevant data are contained in: Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		There are no remediation and verification reports applicable to the site.
### Supporting Information ### Source information incidents ### The following reports are attached as supporting information: ### Appendix C: ### Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. ### Source information identifying environmental setting and pollution incidents ### The following reports are attached as supporting information: ### Appendix B: ### Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. ### Appendix C: ### Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. ### Appendix D: ### Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. #### Historical Ordnance Survey plans	(where available)	
Hydrock, O9 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, O9 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	Baseline soil and	All relevant data are contained in:
Hydrock, 09 December 2023, Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Supporting Information Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. Appendix C: Hydrock, 09 December 2023, Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	groundwater reference	» Appendix C:
Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: » Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. » Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans	data	
Source information identifying environmental setting and pollution incidents The following reports are attached as supporting information: » Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. » Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		
incidents The following reports are attached as supporting information: » Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. » Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		18443-HYD-XX-XX-RP-GE-1005.
 » Appendix B: Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. » Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans 	Supporting Information	, ,
Hydrock, 31 January 2022. Land adjacent Haldens Parkway, Thrapston. Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. » Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		The following reports are attached as supporting information:
Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002. » Appendix C: Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		» Appendix B:
Hydrock, 09 December 2023. Land adjacent Haldens Parkway, Thrapston. Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		
Ground Investigation Report. Geo-environmental Interpretation. Report. Ref 18443-HYD-XX-XX-RP-GE-1005. » Appendix D: Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		» Appendix C:
Hydrock 23 August 2022. Rectory Farm (Thrapston) Landfill (EPR/BT9879IY) Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		Ground Investigation Report. Geo-environmental Interpretation. Report. Ref
Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-GE-0003. Historical Ordnance Survey plans		» Appendix D:
• •		Hydrogeological Risk Assessment Review. Report. Ref 23880-HYD-XX-XX-RP-
Included in Appendix C of Desk Study report referenced above.		Historical Ordnance Survey plans
		Included in Appendix C of Desk Study report referenced above.
Site reconnaissance		Site reconnaissance
Presented in Section 2.3 of Desk Study report referenced above.		Presented in Section 2.3 of Desk Study report referenced above.
Historical investigation, assessment, remediation, verification reports		Historical investigation, assessment, remediation, verification reports
» Investigation		» Investigation



2.0 Condition of the land at permit issue	
	Ground Investigation Report referenced above
	» Assessment
	Ground Investigation Report referenced above
	» Remediation
	Not applicable
	» Verification
	Not applicable



3.0 Permitted Activities

Permitted activities

Bespoke, site-specific Deposit for Recovery permit, to allow the recovery and re-use of materials from the Rectory Farm Landfill to create landscape bunds in accordance with the planning permission for the development.

Additionally, the permit will allow stabilisation/solidification, screening/blending and hand picking.

Separately a Mobile Plant Permit will be deployed to excavate and segregate all Secondary Materials.

Primary and other non-waste materials will be re-used in accordance with a

Materials Management Plan prepared in accordance with the DoWCoP

Non permitted activities to be undertaken

Document references for:

- » plan showing activity layout; and
- » environmental risk assessment.

Plan

Drawing references:

- » 18443-HYD-XX-ZZ-DR-GE-1028 Landscape Bund Layout (bund footprint is Deposit for Recovery Area) at Appendix A;
- » 18443-HYD-XX-ZZ-DR-GE-1034_S2-P01_Cross-sections_Bund

Environmental Risk Assessment

- » Hydrock Report reference 18443-HYD-XX-XX-RP-GE-1002-S2-P05; Land adjacent Halden's Parkway, Thrapston. Desk Study Report.
- » Hydrock Report reference 18443-HYD-XX-XX-RP-GE-1005-S2-P07; Land adjacent Halden's Parkway, Thrapston. Ground Investigation Report. Geoenvironmental Interpretation.
- » Hydrock Report reference 18443-HYD-XX-XX-RP-GE-3003-S2-P01; Land adjacent Halden's Parkway, Thrapston. Detailed Quantitative Risk Assessment for Impact of Recovered Waste on Controlled Waters.




Appendix A Drawings





— THE SITE








THE SITE


P03	Client Name					
PU3	NT	15.12.21	NT	15.12.21	AB	15.12.21
P02						
PU2	SD	08.11.21	NT	08.11.21	AB	08.11.2
P01	FIRST ISSUE					
FU1	SD	16.08.21	NT	16.08.21	AB	16.08.2
REV	REVISION NO	TES/COMN	IENTS			
nev.	DRAWN BY	DATE	CHECKED B	Y DATE	APPROVED B	DATE
ł	lydı	roc	k	TEL: 01604 E-Mail: nor	on NN6 8LD	drock.com
Εq	uites Ne	wiands	s (Inrap	ston E	ast) Lim	ited
PRO	UITES NE UIECT IND ADJA HRAPSTO	ACENT				ited
PRO	IND ADJA	ACENT				ited
PRO LA TH	IND ADJA	ACENT)N	HALDE			ited
PRO LA TH	ND ADJA NRAPSTO	ACENT)N	HALDE			ited
PRO LA TH	ND ADJA NRAPSTO	ACENT)N	HALDE			ited
PRO LA TH	ND ADJA NRAPSTO	ACENT DN FION P	HALDE		KWAY	ited
PROLATIFICATION OF THE SITE OF	IND ADJU HRAPSTC	ACENT DN FION P	HALDE	NS PAR	wing	STATUS S2













Appendix B Desk Study Report. Ref 18443-HYD-XX-XX-RP-GE-1002



Appendix C Ground Investigation Report.

Geo-environmental
Interpretation. Report. Ref 18443HYD-XX-XX-RP-GE-1005



Appendix D Hydrogeological Risk
Assessment Review. Report. Ref
23880-HYD-XX-XX-RP-GE0003