Indicative Landscape Plan: Gadebridge Park **River Restoration**



MILLINI MARTINI Club green Manor House Walls Proposed location for footbridge and new gauging station Charter Tower Bowling club house 0-Site of late 18th century gardens Existing perched channel New channel to join existing: alignment to be finalised at detailed design stage **Existing features:** Ρ C shown in black (*italic*) Existing Bury Mill gauging station The Bury **Proposed features:** shown in blue (plain text) Site of former Bury Mill C Flood culvert kept operational. Proposed new paths Existing outfall to piped spring flows Queensway (indicative routes) < Version 7-0

11/7/18

Environment