



# Sewer Surveys UK Ltd



### ABBREVIATIONS

- B Sewer broken at this point
- BJ Broken joint
- CC Circumferential crack
- CCJ Circumferential crack on joint
- CPR Cured in place repair
- CPRP Cured in place repair
- CM Multiple cracks
- CMJ Cracks multiple on joint
- CN Connection
- CND Loss of vision (slit)
- COW Camera underwater
- CUZ Loss of vision (Camera under water)
- CW Combined water
- CXD Connection defective
- CXI Connection intruding
- DC Diameter of pipe changes
- DEC Silt/debris deposits hard or compacted
- DEE Erosion scale light
- DEEJ Erosion light at joint
- DEF Debris foulings
- DER Debris rubble
- DES Debris silt
- DEX Oversized deposits
- DEZ Other attached deposits
- FC Fracture circumferential
- FCJ Fracture circumferential on joint
- FL Fracture longitudinal
- FM Fracture multiple
- FW Foul water
- GY Gully
- H Hole
- HU Hole at joint
- HPWJ High pressure water jetting
- IR Infiltration running
- IS Infiltration seeping
- JD Joint displaced medium
- JN Junction
- JXD Junction defective
- LD Line down
- LL Line left
- LR Line right
- LU Line up
- NCA No camera access
- MH Manhole
- CJ Open joint medium
- DBP Destruction (external pipe or cable)
- REM General observation at this point with explanation
- RFJ Roots fine at joint
- RFJL Roots mass at joint
- RE Rodding eye
- RT Road trip
- SW Surface Water
- SA Survey Abandoned
- UTL Unable to locate
- UTR Unable to raise
- UTS Unable to survey
- WL Water level
- XP Collapse to pipe



Itemref	Quantity	Title/Name, designation, material, dimension etc	Article No./Reference
PR	Designed by	AF	21/354
	Checked by	AE	21/07/21
	Approved by	AE	21/07/21

**Sewer Surveys UK**

Holmfirth Dyers

Holmfirth

0

2/4

Sheet