

Section Inspection - 25/06/2024 - RWP2X




Item No. 33	Insp. No. 1	Date 25/06/24	Time 11:24	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Not Specified	PLR RWP2X
Operator SS	Vehicle CCTV	Camera Pushrod	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified		

Town or Village:	Bentham	Inspection Direction:	Upstream	Upstream Node:	RWP2
Road:	Station Road	Inspected Length:	12.34 m	Upstream Pipe Depth:	
Location:	Other pedestrian area	Total Length:	12.34 m	Downstream Node:	S27A
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:		Pipe Material:	Vitrified clay pipe (i.e. all clayware)		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection of condition	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:107	Position [m]	Code	Observation	MPEG	Photo	Grade
--------	-------	--------------	------	-------------	------	-------	-------



Construction Features				Miscellaneous Features							
Structural Defects				Service & Operational Observations							
STR No.	Def	STR Peak	STR Mean	STR Total	STR Grade	SER No.	Def	SER Peak	SER Mean	SER Total	SER Grade
0		0.0	0.0	0.0	1.0	0		0.0	0.0	0.0	1.0



Section Inspection - 11/08/2022 - S27AX




Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
24	1	11/08/22	14:23	Not Specified	No Rain Or Snow	Not Specified	S27AX
Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID		
HS	CCTV	Pushrod	Not Specified	Not Specified	Not Specified		

Town or Village:	Bentham	Inspection Direction:	Downstream	Upstream Node:	S27A
Road:	Station Road	Inspected Length:	28.79 m	Upstream Pipe Depth:	
Location:	Other pedestrian area	Total Length:	28.79 m	Downstream Node:	S27
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:		Pipe Material:	Vitrified clay pipe (i.e. all clayware)		
Year Constructed:	Not Specified	Lining Type:	Cured in place lining		
Inspection Purpose:	Post completion inspection of repairs or renovations	Lining Material:	Fibre reinforced plastics		

Comments:
Recommendations:

Scale:	1:250	Position [m]	Code	Observation	MPEG	Photo	Grade
--------	-------	--------------	------	-------------	------	-------	-------

Depth: m
S27A



0.00	MH	Start node, manhole, reference: S27A	00:00:00	
0.00	WL	Water level, 5% of the vertical dimension		
0.42	LR	Line deviates right: Medium	00:00:12	
1.54	S01	RPL	Point repair, localised lining from 12 o'clock to 12 o'clock, start: Patch repair	00:00:15
2.70	F01	RPL	Point repair, localised lining from 12 o'clock to 12 o'clock, finish: Patch repair	00:00:18
3.60	LR	Line deviates right: Slight	00:00:20	
8.09	JN	Junction at 10 o'clock, diameter: 100mm	00:00:25	
24.99	JN	Junction at 12 o'clock, diameter: 100mm	00:00:48	
27.22	RPL	Point repair, localised lining from 12 o'clock to 12 o'clock: Patch repair	00:00:50	
28.79	CPF	Finish node, catchpit, reference: S27	00:01:02	

S27
Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No.	Def	STR Peak	STR Mean	STR Total	STR Grade	SER No.	Def	SER Peak	SER Mean	SER Total	SER Grade
0		0.0	0.0	0.0	1.0	0		0.0	0.0	0.0	1.0

