



Photograph 1: Site entrance with motorised gate and palisade fencing.



Photograph 2: Southwest façade, with electricity substations to right of image and S1 emission monitoring point to left of image.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 3: Southeast façade with electricity substation in front of building and emissions stack A1 visible.



Photograph 4: Coolers at northeast end of the site.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 5: Concrete pad in main yard. Existing weighbridge is visible at the top right hand side of the image.



Photograph 6: Northeastern edge of main yard with bank and site boundary palisade fence in background.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 7: View of northeast side of the building from main yard.



Photograph 8: View of northwest corner of the site from the main yard.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 9: View of facility looking south from the main yard. Reception hall is to the left of the image and stack visible in background.



Photograph 10: Southeast corner of yard. Diesel tank on right hand side of image.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 11: Fuel reception hall.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 12: Existing equipment inside processing building.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 13: Conveyors inside processing building. Hard standing in good condition.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 14: View of stack from inside the building.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	



Photograph 15: Existing extraction point.

Rev:	Date:	Desc:	Client:	Job no.:
0	October 2022	Original	Biomass No.4 UK Limited Plymouth EfW Facility	SOL_21_P024_COG October 2022
			Annex Title:	
			Site Photographs	