











Hopper >50mm aggregate Initial Screen Nfe >50mm Oversize Picking 0 - 50mm FE >50mm 50+ mm 0 – 50mm 2nd Screen 0-12mm Nfe 20 - 50mm Zorba / Stainless Nfg 12 - 20mm 12 - 20 mm 20 - 50mm 0-12mm Nfe 6 - 12mm 3rd Screen 0 - 6mm Nfg 0 - 6mm 6-12 mm FE 0 - 50mm 0-50mm IBAA

Figure 1: Process flow diagram