


IF IN DOUBT ASK

System: Anodising	Area: Etch Tank -5	Op: n/a
Process: Tank Leakage	Description: Etch Tank-5 Leakage Procedure	Sht: 2of 1

Safety equipments must be worn




When temperature reach to about 50 degree celsius start transferring etch from the etch tank to emergency IBC with the help of submersible pump . Use 15 IBC to store all the etch solution from the etch tank . Once tank gets empty , label all the IBC (which tank , which etch) . Now etch tank is ready for repair .



Transfer all the IBC to the emergency containment area .

Coshh data sheet are available for all the chemicals used in the anodising process. Before attempting any maintenance Work on the tanks or chemical handling equipment refer to the data sheet

Notes:			
Author: N. Mistry	Verified:	Approved:	