

DRAINAGE REQUIRING ATTENTION - South Denes Only:

- 100Ø clay pipe collapsed from G31
- Pump not working correctly
- GA, G36 & G39 pipes blocked
- Manhole on quay silted up
- MA & MB to be blocked/filled if redundant 7no shut-off valves to be installed

DRAIN MAINTENANCE - all areas:

- All gullies to be kept clear of silt and obstructions
- Pump to be serviced regularly
- Interceptors to be regularly emptied

EMERGENCY STRATEGY - South Denes A & B:

- Lay containment booms across quayside and roads • Block all gullies in containment area if possible
- Block manhole MH3 or Outfall if possible
- Block manhole MH25
- Monitor sewer downstream of MH25
- Pump away from MH3, MH24

EMERGENCY STRATEGY - South Denes C1, C2 & C3:

- Lay containment booms across quayside and roads
- Block all gullies in containment area if possible
- Block manhole MH6 or Outfall if possible Block manhole MH25
- Monitor sewer downstream of MH25
- Pump away from MH6, MH24


EMERGENCY STRATEGY - Gas House Quay:


- Lay containment booms across quayside
- Block gullies G1, G2, G3, G6 & channel if possible
- Block manholes MH3 & MH5 if possible • Block & monitor sewers downstream of MH3 & MH5
- Pump away from MH3, MH5 & downstream sewer

NOTES:

- 1. This drawing to be read in conjunction with Drains-R-Us drainage report dated 18th March 2011
- 2. All dims in mm u.n.o.
- 3. All dimensions & specifications subject to review during detailed design
- 4. Positions of manholes, gullies and piping are shown indicatively only
- 5. Spillage flow will depend on gradients, to be determined by topographic survey prior to construction

TENDER







Connaught Road Attleborough Norfolk NR17 2BW Telephone: (01953) 452001 Fax: (01953) 456955 E-mail: pdc@plandescil.co.uk www.plandescil.co.uk

civil . structural . environmental . surveying



Client

ASCO UK Ltd.

South Denes Rd. & Southtown Rd. **Great Yarmouth**

Tank Bund Renovation

Drawing Title

Storm Drainage -

Layout & Emergency Procedure

Scale	Date	Drawn By
As shown	08-02-2011	RF
Drg. No.	16447-004	