


# Trent Valley IDB Main River Maintenance

**Service Plan**  
**Map Ref: 4110-1**  
**Watercourse: Cocker Beck**

Primary contact Ashley Reeves  
 Maintenance Lead  
 xxxx


Secondary contact Albert Jordana  
 Patch Lead  
 xxxx


Field Team contact  
 Neil Clayton  
 xxxx



Grass Cut	Floodbank	Bridge & Debris	Tree & Bush	Weedcut
Left Bank	Right Bank			

1	conf. River Trent SK6750743732				
2	Low dham Station SK6735345946	M4 2x/yr			
3	Marlock Bridge SK6736245577	M4 2x/yr			
4	A612, Low dham SK6709646219		12x /yr	TB3 Every 3 years	W7 1x /yr
5	Brook House, Ton Lane, Low dham SK6671246582	M4 2x/yr			
6	rear of Low dham CE School, Low dham SK6660546802				






**Trent Valley IDB  
Main River Maintenance**

**Map Ref: 4110 - 2  
Cocker Beck  
Bridge & Debris Run**

**Primary Contact  
Ashley Reeves  
Maintenance Lead**

**Secondary Contact  
Albert Jordana  
Patch Lead**

**Field Team Contact  
Neil Clayton**



**Monthly Inspections**

**Actions:**  
No Blockage - Record NB on log sheet


Small Blockage - Record B on log sheet and remove in accordance with generic RAMS and OI's

Severe Blockage - Record SB on log sheet and report in accordance with contact hierarchy


**Legend**

**Chainage (m), Location**

- 0m, Foot Access - Trent Lane - Foot Bridge
- 360m, Foot Access - Lowdham Caravans - Bridge
- 765m, Vehicle Access - Brookland Farm - Bridge
- 900m, Foot Access - Marhill Service Centre - Foot Bridge
- 1135m, Vehicle Access - The Cedars - Bridge
- 1280m, Vehicle Access - Grange Farm - Bridge
- 1400m, Vehicle Access - STW pump station - Bridge
- 1850m, Vehicle Access - Cottage Pasture Ln - Bridge
- 2090m, Vehicle Access - Lowdham Road - Bridge
- 2440m, Vehicle Access - Caythorpe Road - Bridge
- 2478m, Foot Access - Railway Bridge
- 2590m, Vehicle Access - Blenheim Av - Bridge
- 2700m, Vehicle Access - Lime Tree Gardens - Bridge
- 2745m, Vehicle Access - Merevale Close - Bridge
- 2846m, Vehicle Access - Nottingham Road - Bridge
- 3085m, Foot Access - Playing Field - Foot Bridge
- 3250m, Foot Access - Playing Field - Foot Bridge
- 3450m, Vehicle Access - Ton Lane - Bridge



- Part of N5 high priority flood patrol
- Part of N5 low priority flood patrol
- Not part of flood patrol



Map Ref: 4110 - 2 Cocker Beck Bridge & Debris Run

No Blockage				NB
Blockage removed following Generic RAMS & OI's				B
Severe blockage report following contact hierarchy				SB
Chainage	Inspection #1 April	Inspection #2 May	Inspection #3 June	Inspection #4 July
0 Trent Lane				
360 Lowdham Caravans				
765 Brookland Farm				
900 Marhill Service Centre				
1135 The Cedars				
1280 Grange Farm				
1400 STW pump station				
1850 Cottage Pasture Lane				
2090 Lowdham Road				
2440 Caythorpe Road				
2478 Railway Bridge				
2590 Belnheim Avenue				
2700 Lime Tree Gardens				
2745 Merevale Close				
2846 Nottingham Road				
3085 Playing Field Foot Bridge				
3250 Playing Field Foot Bridge				
3450 Ton Lane				

Map Ref: 4110 - 2 Cocker Beck Bridge & Debris Run



No Blockage				NB
Blockage removed following Generic RAMS & OI's				B
Severe blockage report following contact hierarchy				SB
Chainage	Inspection #5 August	Inspection #6 September	Inspection #7 October	Inspection #8 November
0 Trent Lane				
360 Lowdham Caravans				
765 Brookland Farm				
900 Marhill Service Centre				
1135 The Cedars				
1280 Grange Farm				
1400 STW pump station				
1850 Cottage Pasture Lane				
2090 Lowdham Road				
2440 Caythorpe Road				
2478 Railway Bridge				
2590 Belnheim Avenue				
2700 Lime Tree Gardens				
2745 Merevale Close				
2846 Nottingham Road				
3085 Playing Field Foot Bridge				
3250 Playing Field Foot Bridge				
3450 Ton Lane				

Map Ref: 4110 - 2 Cocker Beck Bridge & Debris Run

No Blockage				NB
Blockage removed following Generic RAMS & OI's				B
Severe blockage report following contact hierarchy				SB
Chainage	Inspection #9 December	Inspection #10 January	Inspection #11 February	Inspection #12 March
0 Trent Lane				
360 Lowdham Caravans				
765 Brookland Farm				
900 Marhill Service Centre				
1135 The Cedars				
1280 Grange Farm				
1400 STW pump station				
1850 Cottage Pasture Lane				
2090 Lowdham Road				
2440 Caythorpe Road				
2478 Railway Bridge				
2590 Belnheim Avenue				
2700 Lime Tree Gardens				
2745 Merevale Close				
2846 Nottingham Road				
3085 Playing Field Foot Bridge				
3250 Playing Field Foot Bridge				
3450 Ton Lane				




M4 Grass control






M5 Grass control




Annual maintenance this side only






### W4 Weed control



Distance between aquatic margin centres



Approx. 20m of aquatic margin



Typical growth before maintenance





Maintain short lengths of approx. 20m of aquatic margin on alternating sides



### TB3 Tree and bush management

Tree and bush work can usually be undertaken between September and Mid-February, unless nesting birds are present.



Consider retaining removed trees and bushes for re-use in another location, attaching securely to a river bed to encourage restoration river

Cut to bank height

All roots to remain in situ



# ME2 Mowing Raised Banks

