

Roxby Landfill Site – August 2022

Introduction

We are pleased to be bringing you the latest Environment Agency update on our compliance work at Roxby Landfill operated by Biffa Waste Services Ltd.

Latest compliance news

Odour

- The number of odour reports received in August was 12. This can be seen in the graph below.
- An odour survey in the community was undertaken on 09/08/22. The survey included the Thealby, Winterton and Roxby areas. No landfill odour was detected.


Engineering

- Temporary capping is now completed on the north flank which is required to control odour. We have validated the progress of this work using our Environment Agency Drone.
- Permanent gas wells have now also been installed in cell 13a. This work is a requirement to ensure Biffa remains compliant with its permit condition for landfill gas management.

Compliance work

- As part of our compliance work, we are currently looking at the main waste streams being received at Roxby Landfill. The focus is ensuring the required sampling and analysis is completed, and that Biffa's Management procedures are followed relating to waste acceptance. This information will be assessed against the conditions of the sites environmental permit that specifically relate to this.

Odour reports received by the Environment Agency through our incident hotline



Roxby Community Liaison Group

The next meeting is scheduled to be held virtually on 14 September 2022. Should you wish to attend this meeting please email LNenquiries@environment-agency.gov.uk.

Next update

We will provide our next update at the end of September 2022.

If you would like to provide feedback on how useful you found this update, please email:
LNenquiries@environment-agency.gov.uk

**Please continue to use our Incident Hotline 0800 80 70 60
to report odours**