



SITE 1: (2x Samples)

1. @ 1.1m depth I.D. 45208816 Site 1, TP1 Northern 1.1 Approx. Grid Ref. x= 436807, y= 336195
2. @ 2.8m depth I.D. 45208817 Site 1, TP1 Northern 2.8 Approx. Grid Ref. x= 436807, y= 336195

SITE 2: (1x Sample)

1. @ 2.0m depth I.D. 45208818 Site 2, TP2 South Approx. Grid Ref. x= 436785, y= 336160

SITE 3: (1x Sample)

1. @ 2.0m depth I.D. 45208819 Site 3, TP3 adjacent to 3.0, Approx. Grid Ref. x= 436822, y= 336139

Site Address: 22LF, Downing Road West Meadows Industrial Estate Derby, DE21 6HA		OIL POLLUTION SERVICES Ltd. <small>OIL POLLUTION SERVICES LTD. BUILDING 51, WELLS, REDDERSHIRE, MK45 4HT, COMPANY REG. 3030749.</small>	
		SITE CONDITION REPORT	
RECYCLING PLANT		NUMBER: 22LF	
DATE: NTS		DATE: 17.10.2014	
JOB NO: 01132		01132-16-00	