



NOTES
 1. TOPOGRAPHIC SURVEY INFORMATION SUPPLIED BY SINGLETON BIRCH LTD. REF: 3185 0420 3D.DWG, DATE RECEIVED: 24.09.2020.

LEGEND

| | |
|--|--|
| | DEPOSIT OF WASTE FOR RECOVERY ACTIVITY BOUNDARY |
| | ENVIRONMENTAL PERMIT BOUNDARY - CAMP WOOD |
| | TOPOGRAPHIC SURVEY LEVEL CONTOURS (mAOD) |
| | BH3A GROUNDWATER MONITORING BOREHOLE - WELTON CHALK |
| | GROUNDWATER LEVEL (MAR 2020) |
| | INDICATIVE APPROXIMATE GROUNDWATER CONTOURS (MAR 2020) |

Singleton Birch ...first in lime

SLR global environmental solutions
 3RD FLOOR THE BREW HOUSE JACOB STREET BRISTOL, BS2 0EQ
 T: 01179 064280 www.slrconsulting.com

MELTON ROSS WESTERN QUARRY
 HYDROGEOLOGICAL RISK ASSESSMENT
GROUNDWATER CONTOURS (WELTON CHALK)

HRA2

Scale: 1:5000 @ A2 Date: OCTOBER 2020

416.00075.00104.18.HRA2.0A_GW_Conts_Welton.dwg