



- Key:**
- Permit boundary
  - Access gate
  - Access to Motocross Track
  - Area 1- Soil washing and non-hazardous crushing / screening area
  - Area 2- Hazardous soil washing area
  - Area 3- Asbestos picking and treatment area
  - Area 4- Soil manufacturing area
  - Downwind asbestos monitoring location (dependent on wind conditions)
  - Upwind asbestos monitoring location (dependent on wind conditions)
  - Downwind particulate monitoring location
  - Asbestos monitoring point
  - Soak away location
  - + Visual site boundary inspection location / sniff test location
  - Weather station

- Notes:**
1. Asbestos reassurance monitoring will be undertaken during operational activities in Area 3.
  2. Particulate monitoring will be undertaken with two Osiris monitors along the downwind boundary of the site during operational activities.
  3. Visual site inspections for dust will occur on a daily basis during operational activities.
  4. Only clean surface water from roof runoff to discharge to sealed soak away.

Monitoring Location Coordinates		
ID	X- Coordinate	Y- Coordinate
S1	466472	398003
DM1	466664	398132
DM2	466635	398075
SA1	466521	398023
SA2	466516	398007
D1	466491	398063
D2	466505	398038
D3	466513	398015
U1	466448	398022
U2	466441	397991
U3	466467	397976

Rev.	Details	Drawn Chkd.	Date
------	---------	-------------	------

Project  
**193433**  
**Fingingley Quarry**

Title  
**Monitoring Plan**

**AA Environmental Ltd**  
 Units 4-8  
 Cholswell Court  
 Shippon Abingdon  
 Oxon OX13 6HX  
 T: (01235) 536042  
 F: (01235) 523849  
 info@aae-ltd.co.uk  
 www.aae-ltd.co.uk

Scale	Date	Nov '20	Drg. No.	Rev.
1:1,000@A3	Drawn	Chkd.	193433/D/004	A