



# Silkstone

## Environmental Ltd

www.silkstoneenvironmental.co.uk

7, Hall Annex, Thorncliffe Park, Chapeltown, Sheffield, S35 2PH  
 Tel (0114) 2573487 Fax (0114) 2573459

- 120.41 Monitoring borehole location with groundwater elevation mAOD
- Springs/issues with elevation mAOD
- Potential emission from 80YD Rock
- Lateral extent of Eiland Flage
- Lateral extent of 80 Yard Rock

Client:	<b>Marshalls</b>	Drawing No.	ESSD 7a	Rev
Project:	PASTURE HOUSE QUARRY WASTE RECOVERY PERMIT APPLICATION		Project No. 20293	
Plan Title:	LOCAL HYDROGEOLOGY - UPPER SANDSTONE		Date: Sept 2021	
			Scale: 1:10000 @ A4	
			Drawn: PS	
			Chkd:	