



Silkstone

Environmental Ltd

www.silkstoneenvironmental.co.uk

7, Hall Annex, Thorncliffe Park, Chapeltown, Sheffield, S35 2PH
 Tel (0114) 2573487 Fax (0114) 2573459

- 3B 120.41 Monitoring borehole location with groundwater elevation mAOO
- Springs/issues with elevation mAOO
- Potential emission from 80YD Rock
- Lateral extent of Eiland Flags
- Lateral extent of 80 Yard Rock

Client:



Drawing No.
ESSD 7b

Rev

Project:

PASTURE HOUSE QUARRY
WASTE RECOVERY PERMIT APPLICATION

Project No. 20293

Date: Sept 2021

Plan Title:

LOCAL HYDROGEOLOGY - 80 YARD ROCK

Scale: 1:10000 @ A4

Drawn: PS

Chkd: