



## EXTRACTION EQUIPMENT

This is to certify that  
the extraction system installed at:

Company

**Lotus Anodising**

System

**Fume Extraction System - LEV01**

Located

**R Seal Superior- Hot Water Sealing NN8 6XY**

**has been thoroughly inspected and tested on:**

**November 2019**

**and is deemed to be operating  
efficiently at the time of inspection**

**Signed:**

**Next inspection due on:**

**November 2020**