

Report Details

Filled By	Paul Harrison
User Email	paul.harrison@andel.co.uk
Started At	07-Dec-2023 12:34:46
Completed At	07-Dec-2023 12:45:49
Synced At	07-Dec-2023 12:46:14
Time Taken	11 Min 3 Sec

Form Details

Form Code	SM01
Form Title	Site Memo
Filled Version	10
Current Version	10
Created At	07-Sep-2022 08:21:23
Last Modified	07-Sep-2022 08:52:16

JOB SHEET DETAILS

PROS Number (If Available)	
Customer:	halamshire hospital
Andel Division :	PPL
Job Type (IWS):	
Job Type (PPL):	OSCI Remedials
Job Type (Floodline):	
Job Type (Other):	
Order Ref No:	
Call Date:	07-Dec-2023
Start Date:	07-Dec-2023

Site Address:

Building Name	
Building Number	
Address Line 1	Royal Hallamshire Hospital
Address Line 2	Glossop Road
Address Line 3	
Town or City	Sheffield
County	South Yorkshire
Postcode	S10 2JF

Manually Enter Site Address:	No
Building Name:	
Building Number:	
Address Line 1:	
Address Line 2:	
Town or City:	
County:	
Postcode:	
Engineers Name:	Paul Harrison
Contact Name:	
Contact Number:	




WORK DONE

Work To Be Done:	tank inspection and fuel sampling
Actual Work Done:	as above 8tanks inspected new generators being installed
Travelling Time:	01:00:00
Arrival Time At Site:	08:00:00
Departure Time From Site:	01:00:00
Time Spent On Site:	07:00


MATERIALS USED

Enter Material Used Details

Description of Material Used:	
Quantity:	
Product Code:	

Miscellaneous Parts Used:	
NOTES:	
Work Completed:	Yes
Completion Date:	07-Dec-2023
Notes:	
Photographs (If required): <div style="text-align: center;">  </div>	
Additional Photographs Required?	No
Additional Photographs <div style="text-align: center;">  </div>	
Engineer Signature: <div style="text-align: center;">  </div>	
Is Customer Present?	Yes

Customers Signature:

A handwritten signature in black ink, featuring a large, stylized 'Z' or '2' followed by a series of loops and a long horizontal stroke extending to the right.