

Individual Separator/Interceptor Inspection Report




SITE INFORMATION

Client Name **Royal Hallamshire Hospital**
Client Address **Glossop Road**
Sheffield
S10 2JF

DATE **18/11/2024**

Inspection carried out by **Josh Atkinson**
Job Number **PROS116645**
Number of tanks on this site **2**

	Interceptor 2	Interceptor Location	Multi storey car park
			



Is the manufacturer's data label intact for this unit?	No
Have you been shown a log of servicing?	No
Date of Last inspection / service	23/05/2024

Make of Interceptor	Could not Establish		Serial Number		
Type of Interceptor	Bypass		If Bypass – is it in?		Free-Flow Mode
Interceptor Class	Class 1				
Approx. Total capacity of Interceptor	Known 3000	Oil capacity	Unknown	Silt capacity	Unknown
Safety Measures Required? 2 person lift		If 'Other' please specify			

HIGH OIL LEVEL ALARM SYSTEM	
Is alarm device fitted?	No
Notes	

Individual Separator/Interceptor Inspection Report

VISUAL INSPECTION OF MANHOLE ACCESS COVER

Photo	Defects/Damage
Lid 1 	Defects/Damage? No
Lid 2 	Defects/Damage? No
Lid 3	Defects/Damage? No

Individual Separator/Interceptor Inspection Report



VISUAL INSPECTION OF TURRET/ACCESS SHAFT

Approximate depth in mm - ground level to top of:

Water	1000	Alarm	N/A	Base	2000
-------	------	-------	-----	------	------

Photo

Defects/Damage

OIL DEPTH

Chamber	Depth (mm)
1	0
2	0
3	0

SILT DEPTH

Chamber	Depth (mm)
1	0
2	0
3	0

COALESCING FILTER

Is coalescing filter/housing fitted?	No
Is filter visible?	N/A
Are liquid levels different inside and out?	N/A
Is filter sealed properly?	N/A
Is filter easily removable?	N/A
Info taken from Andel IWS Service Worksheets?	N/A



Interceptor Operational Assessment Pass

Is a Service recommended? No

TRAFFIC LIGHT SYSTEM

MANHOLE LIDS	Compliant
INTERCEPTOR	Compliant
ALARM	N/A

Individual Separator/Interceptor Inspection Report



SIGN OFF			
Inspected By	Josh Atkinson	Verification Signature	
Date of Sign Off	18/11/24 06:48		
Additional Notes			