

JP Land Restoration Services Ltd
Warmfield Fishing Grounds Development
Warmfield Lane - Kirkthorpe - WF1 5TH – SE 370 210
Specimen Photographs

The former railway cutting contains semi-stagnant water and has been prone to fly tipping.



Northern Powergrid has chopped trees to protect electrical cables. Some branches reserved to create Herpetaria habitats



JP Land Restoration Services Ltd
Warmfield Fishing Grounds Development
Warmfield Lane - Kirkthorpe - WF1 5TH – SE 370 210
Specimen Photographs

Rough ground at the base of the infill zone to create ponds



Coarse vegetation on the flanks of the cutting



Access Road cut to clear a safe and sight line and pathway under cables



Car park being created and wheel wash installed

