

Photographs of the Quarry Floor at Went Edge Quarry for the Permit Variation. December 2018



Photograph number 1 showing the base of the limestone and the red marl below at 2.4 metres in May 2007.



Photograph number 2 showing the temporary quarry sump on the marl excavated in February 2017 near to the wash plant for the quarrying operation to obtain the limestone and use the red marl for the clay lining of the permanent quarry sump.



Photograph number 3 showing the sump and the wash plant area in the north east corner of the quarry in February 2017. The sump has now been backfilled with compacted limestone fines and marl after dewatering the sump.